

39, 40, 41	4264.12	2213.04	10309.6	680.00	17,626.02	55,995.73	1,224.00	61,035.40
39-1002北小房外墙漏水	314.32	161.02	738.6	50.00	1,274.63	3,086.38	90.00	3,364.16
窗口打胶	95.13	65.32	12.41	5.00	181.50	181.50	9.00	197.84
窗口原密封胶铲除,重新打硅宝结构耐候胶	95.13	65.32	12.41	5.00	181.50	181.50	9.00	197.84
堵漏	97.28	45.37	8.54	5.00	158.75	158.75	9.00	173.04
采用YH东方雨虹对缝聚堵漏	97.28	45.37	8.54	5.00	158.75	158.75	9.00	173.04
接缝处打胶	11.65	14.51	4.21	5.00	31.89	179.86	9.00	196.05
对窗台与外墙面接触处,原密封胶铲除,重新打硅宝结	11.65	14.51	4.21	5.00	31.89	179.86	9.00	196.05
垃圾清理	13.16		3.32	5.00	17.51	87.55	9.00	95.43
人工清理建筑垃圾并装袋,垂直运输短驳	13.16		3.32	5.00	17.51	87.55	9.00	95.43
垃圾装车外运	31.25		700	5.00	767.81	767.81	9.00	836.91
自卸汽车运土(8t以内)(运距25km以内)	31.25		700	5.00	767.81	767.81	9.00	836.91
砂浆抹面找平	14.36	8.25	2.13	5.00	25.98	219.79	9.00	239.57
采用立邦抗裂耐水砂浆,对墙面进行找平	14.36	8.25	2.13	5.00	25.98	219.79	9.00	239.57
涂刷防水涂料2遍	19.86	11.76	2.13	5.00	35.44	599.64	9.00	653.61
涂刷东方雨虹HCA-108屋面外墙高弹性防水涂料1.5mm厚	19.86	11.76	2.13	5.00	35.44	599.64	9.00	653.61
涂刷界面剂	4.77	7.65	1.26	5.00	14.36	202.48	9.00	220.70
提高界面处理剂	4.77	7.65	1.26	5.00	14.36	202.48	9.00	220.70
外墙表面铲除清理	14.73		2.43	5.00	18.02	254.08	9.00	276.95
对原墙面落灰、起皮的地方进行铲除	14.73		2.43	5.00	18.02	254.08	9.00	276.95
外墙涂料	12.13	8.16	1.97	5.00	23.37	434.92	9.00	474.06
外墙溶剂涂料一底二面	12.13	8.16	1.97	5.00	23.37	434.92	9.00	474.06
39-1002南主房外墙漏水	314.32	161.02	738.6	50.00	1,274.63	3,858.96	90.00	4,206.26
窗口打胶	95.13	65.32	12.41	5.00	181.50	181.50	9.00	197.84
窗口原密封胶铲除,重新打硅宝结构耐候胶	95.13	65.32	12.41	5.00	181.50	181.50	9.00	197.84
堵漏	97.28	45.37	8.54	5.00	158.75	158.75	9.00	173.04
采用YH东方雨虹对缝聚堵漏	97.28	45.37	8.54	5.00	158.75	158.75	9.00	173.04
接缝处打胶	11.65	14.51	4.21	5.00	31.89	250.02	9.00	272.52
对窗台与外墙面接触处,原密封胶铲除,重新打硅宝结	11.65	14.51	4.21	5.00	31.89	250.02	9.00	272.52
垃圾清理	13.16		3.32	5.00	17.51	122.57	9.00	143.60
人工清理建筑垃圾并装袋,垂直运输短驳	13.16		3.32	5.00	17.51	122.57	9.00	143.60
垃圾装车外运	31.25		700	5.00	767.81	767.81	9.00	836.91
自卸汽车运土(8t以内)(运距25km以内)	31.25		700	5.00	767.81	767.81	9.00	836.91
砂浆抹面找平	14.36	8.25	2.13	5.00	25.98	305.52	9.00	333.02
采用立邦抗裂耐水砂浆,对墙面进行找平	14.36	8.25	2.13	5.00	25.98	305.52	9.00	333.02
涂刷防水涂料2遍	19.86	11.76	2.13	5.00	35.44	833.55	9.00	908.57
涂刷东方雨虹HCA-108屋面外墙高弹性防水涂料1.5mm厚	19.86	11.76	2.13	5.00	35.44	833.55	9.00	908.57
涂刷界面剂	4.77	7.65	1.26	5.00	14.36	281.46	9.00	306.79
提高界面处理剂	4.77	7.65	1.26	5.00	14.36	281.46	9.00	306.79
外墙表面铲除清理	14.73		2.43	5.00	18.02	353.19	9.00	384.98
对原墙面落灰、起皮的地方进行铲除	14.73		2.43	5.00	18.02	353.19	9.00	384.98
外墙涂料	12.13	8.16	1.97	5.00	23.37	604.58	9.00	658.99
外墙溶剂涂料一底二面	12.13	8.16	1.97	5.00	23.37	604.58	9.00	658.99
39-102次卧外墙漏水	246.14	140.4	723.2	40.00	1,165.23	5,469.71	72.00	5,961.98
表面垃圾清理	14.73		2.43	5.00	18.02	268.50	9.00	292.67
对原墙面垃圾清理	14.73		2.43	5.00	18.02	268.50	9.00	292.67
窗口打胶	95.13	65.32	1.26	5.00	169.80	339.60	9.00	370.16
窗口原密封胶铲除,重新打硅宝结构耐候胶	95.13	65.32	1.26	5.00	169.80	339.60	9.00	370.16
大理石缝隙处打胶	11.65	14.51	4.21	5.00	31.89	950.32	9.00	1,035.85
大理石原密封胶铲除,重新打硅宝结构耐候胶	11.65	14.51	4.21	5.00	31.89	950.32	9.00	1,035.85
接缝处打胶	35.25	21.52	4.21	5.00	64.03	1,335.67	9.00	1,455.88
对大理石与外墙面接触处,原密封胶铲除,重新打硅宝	35.25	21.52	4.21	5.00	64.03	1,335.67	9.00	1,455.88

垃圾清理	13.16		3.52	5.00	17.51	87.55	9.00	95.43
人工清理建筑垃圾并装袋, 垂直运输短驳	13.16		3.52	5.00	17.51	87.55	9.00	95.43
垃圾装车外运	31.25		700	5.00	767.81	767.81	9.00	836.91
自卸汽车运土 (8t以内) (运距25km以内)	31.25		700	5.00	767.81	767.81	9.00	836.91
涂刷防水涂料2遍	33.32	24.54	3.36	5.00	64.28	1,245.10	9.00	1,357.16
涂刷东方雨虹HCA121透明防水涂料	33.32	24.54	3.36	5.00	64.28	1,245.10	9.00	1,357.16
涂刷界面剂	11.65	14.51	4.21	5.00	31.89	475.16	9.00	517.92
墙高界面处理剂	11.65	14.51	4.21	5.00	31.89	475.16	9.00	517.92
39-102客厅南阳台外窗翻水	246.14	140.4	723.2	40.00	1,165.23	5,268.89	72.00	5,743.08
表面垃圾清理	14.73		2.43	5.00	18.02	255.88	9.00	278.91
对草墙而垃圾清理	14.73		2.43	5.00	18.02	255.88	9.00	278.91
窗口打胶	95.13	65.32	1.26	5.00	169.80	339.60	9.00	370.16
窗口原密封胶铲除, 重新打硅宝结构耐候胶	95.13	65.32	1.26	5.00	169.80	339.60	9.00	370.16
大理石缝隙处打胶	11.65	14.51	4.21	5.00	31.89	905.68	9.00	987.19
大理石原密封胶铲除, 重新打硅宝结构耐候胶	11.65	14.51	4.21	5.00	31.89	905.68	9.00	987.19
接缝处打胶	35.25	21.52	4.21	5.00	64.03	1,272.92	9.00	1,387.48
对大理石与外墙而接缝处, 原密封胶铲除, 重新打硅宝	35.25	21.52	4.21	5.00	64.03	1,272.92	9.00	1,387.48
垃圾清理	13.16		3.52	5.00	17.51	87.55	9.00	95.43
人工清理建筑垃圾并装袋, 垂直运输短驳	13.16		3.52	5.00	17.51	87.55	9.00	95.43
垃圾装车外运	31.25		700	5.00	767.81	767.81	9.00	836.91
自卸汽车运土 (8t以内) (运距25km以内)	31.25		700	5.00	767.81	767.81	9.00	836.91
涂刷防水涂料2遍	33.32	24.54	3.36	5.00	64.28	1,186.61	9.00	1,293.40
涂刷东方雨虹HCA121透明防水涂料	33.32	24.54	3.36	5.00	64.28	1,186.61	9.00	1,293.40
涂刷界面剂	11.65	14.51	4.21	5.00	31.89	452.84	9.00	493.60
墙高界面处理剂	11.65	14.51	4.21	5.00	31.89	452.84	9.00	493.60
39-201南卧室东外墙翻水	314.32	161.02	738.6	50.00	1,274.63	3,822.84	90.00	4,166.91
窗口打胶	95.13	65.32	12.41	5.00	181.50	0.00	9.00	0.00
窗口原密封胶铲除, 重新打硅宝结构耐候胶	95.13	65.32	12.41	5.00	181.50	0.00	9.00	0.00
堵漏	97.28	45.37	8.54	5.00	158.75	317.50	9.00	346.08
采用YH东方雨虹对缝漏堵漏	97.28	45.37	8.54	5.00	158.75	317.50	9.00	346.08
接缝处打胶	11.65	14.51	4.21	5.00	31.89	248.74	9.00	271.13
对窗台与外墙而接缝处, 原密封胶铲除, 重新打硅宝	11.65	14.51	4.21	5.00	31.89	248.74	9.00	271.13
垃圾清理	13.16		3.52	5.00	17.51	123.57	9.00	133.60
人工清理建筑垃圾并装袋, 垂直运输短驳	13.16		3.52	5.00	17.51	123.57	9.00	133.60
垃圾装车外运	31.25		700	5.00	767.81	767.81	9.00	836.91
自卸汽车运土 (8t以内) (运距25km以内)	31.25		700	5.00	767.81	767.81	9.00	836.91
砂浆抹面找平	14.36	8.25	2.13	5.00	25.98	303.97	9.00	331.33
采用立邦抗裂耐水砂浆, 对墙面进行找平	14.36	8.25	2.13	5.00	25.98	303.97	9.00	331.33
涂刷防水涂料2遍	19.86	11.76	2.13	5.00	35.44	829.30	9.00	903.94
涂刷东方雨虹HCA-108厨卫外墙高弹性防水涂料1.5mm厚	19.86	11.76	2.13	5.00	35.44	829.30	9.00	903.94
涂刷界面剂	4.77	7.65	1.26	5.00	14.36	280.02	9.00	305.22
墙高界面处理剂	4.77	7.65	1.26	5.00	14.36	280.02	9.00	305.22
外墙表面铲除清理	14.73		2.43	5.00	18.02	351.39	9.00	383.02
对草墙而等灰、起皮的地方进行铲除	14.73		2.43	5.00	18.02	351.39	9.00	383.02
外墙涂料	12.13	8.16	1.97	5.00	23.37	601.54	9.00	655.68
外墙涂料一底二面	12.13	8.16	1.97	5.00	23.37	601.54	9.00	655.68
39-402南阳台窗户	314.32	161.02	738.6	50.00	1,274.63	3,956.93	90.00	4,313.06
窗口打胶	95.13	65.32	12.41	5.00	181.50	0.00	9.00	0.00
窗口原密封胶铲除, 重新打硅宝结构耐候胶	95.13	65.32	12.41	5.00	181.50	0.00	9.00	0.00
堵漏	97.28	45.37	8.54	5.00	158.75	317.50	9.00	346.08
采用YH东方雨虹对缝漏堵漏	97.28	45.37	8.54	5.00	158.75	317.50	9.00	346.08
接缝处打胶	11.65	14.51	4.21	5.00	31.89	261.50	9.00	285.04

对窗台与外墙面接缝处，原密封胶铲除，重新打硅宝胶	11.65	14.51	4.21	5.00	31.89	261.50	9.00	285.04
垃圾清理	13.16		3.52	5.00	17.51	122.57	9.00	133.60
人工清理建筑垃圾并装袋，垂直运输短驳	13.16		3.52	5.00	17.51	122.57	9.00	133.60
垃圾装车外运	31.25		700	5.00	767.81	767.81	9.00	836.91
自卸汽车运土（8t以内）（运距25km以内）	31.25		700	5.00	767.81	767.81	9.00	836.91
砂浆抹面找平	14.36	8.25	2.13	5.00	25.98	319.55	9.00	348.31
采用立邦抗裂防水砂浆，对墙面进行找平	14.36	8.25	2.13	5.00	25.98	319.55	9.00	348.31
涂刷防水涂料2遍	19.86	11.76	2.13	5.00	35.44	871.82	9.00	950.28
涂刷东方雨虹HCA-108屋面外墙高弹性防水涂料1.5mm厚	19.86	11.76	2.13	5.00	35.44	871.82	9.00	950.28
涂刷界面剂	4.77	7.65	1.26	5.00	14.36	294.38	9.00	320.87
墙身界面处理剂	4.77	7.65	1.26	5.00	14.36	294.38	9.00	320.87
外墙表面铲除清理	14.73		2.43	5.00	18.02	369.41	9.00	402.66
对原墙面落灰、起皮的地方进行铲除	14.73		2.43	5.00	18.02	369.41	9.00	402.66
外墙涂料	12.13	8.16	1.97	5.00	23.37	632.39	9.00	689.31
外墙溶剂涂料一底二面	12.13	8.16	1.97	5.00	23.37	632.39	9.00	689.31
39-501主卫生间东侧漏水	314.32	161.02	738.6	50.00	1,274.63	3,406.30	90.00	3,712.77
窗口打胶	95.13	65.32	12.41	5.00	181.50	181.50	9.00	197.84
窗口原密封胶铲除，重新打硅宝结构耐候胶	95.13	65.32	12.41	5.00	181.50	181.50	9.00	197.84
堵漏	97.28	45.37	8.54	5.00	158.75	317.50	9.00	346.08
采用YH东方雨虹对缝嵌堵漏	97.28	45.37	8.54	5.00	158.75	317.50	9.00	346.08
接缝处打胶	11.65	14.51	4.21	5.00	31.89	195.17	9.00	212.74
对窗台与外墙面接缝处，原密封胶铲除，重新打硅宝胶	11.65	14.51	4.21	5.00	31.89	195.17	9.00	212.74
垃圾清理	13.16		3.52	5.00	17.51	87.55	9.00	95.43
人工清理建筑垃圾并装袋，垂直运输短驳	13.16		3.52	5.00	17.51	87.55	9.00	95.43
垃圾装车外运	31.25		700	5.00	767.81	767.81	9.00	836.91
自卸汽车运土（8t以内）（运距25km以内）	31.25		700	5.00	767.81	767.81	9.00	836.91
砂浆抹面找平	14.36	8.25	2.13	5.00	25.98	238.50	9.00	259.97
采用立邦抗裂防水砂浆，对墙面进行找平	14.36	8.25	2.13	5.00	25.98	238.50	9.00	259.97
涂刷防水涂料2遍	19.86	11.76	2.13	5.00	35.44	650.68	9.00	703.24
涂刷东方雨虹HCA-108屋面外墙高弹性防水涂料1.5mm厚	19.86	11.76	2.13	5.00	35.44	650.68	9.00	703.24
涂刷界面剂	4.77	7.65	1.26	5.00	14.36	219.71	9.00	239.48
墙身界面处理剂	4.77	7.65	1.26	5.00	14.36	219.71	9.00	239.48
外墙表面铲除清理	14.73		2.43	5.00	18.02	275.71	9.00	300.52
对原墙面落灰、起皮的地方进行铲除	14.73		2.43	5.00	18.02	275.71	9.00	300.52
外墙涂料	12.13	8.16	1.97	5.00	23.37	472.07	9.00	514.56
外墙溶剂涂料一底二面	12.13	8.16	1.97	5.00	23.37	472.07	9.00	514.56
39-801卧室南阳台漏水	314.32	161.02	738.6	50.00	1,274.63	3,365.87	90.00	3,668.81
窗口打胶	95.13	65.32	12.41	5.00	181.50	181.50	9.00	197.84
窗口原密封胶铲除，重新打硅宝结构耐候胶	95.13	65.32	12.41	5.00	181.50	181.50	9.00	197.84
堵漏	97.28	45.37	8.54	5.00	158.75	317.50	9.00	346.08
采用YH东方雨虹对缝嵌堵漏	97.28	45.37	8.54	5.00	158.75	317.50	9.00	346.08
接缝处打胶	11.65	14.51	4.21	5.00	31.89	191.34	9.00	208.56
对窗台与外墙面接缝处，原密封胶铲除，重新打硅宝胶	11.65	14.51	4.21	5.00	31.89	191.34	9.00	208.56
垃圾清理	13.16		3.52	5.00	17.51	87.55	9.00	95.43
人工清理建筑垃圾并装袋，垂直运输短驳	13.16		3.52	5.00	17.51	87.55	9.00	95.43
垃圾装车外运	31.25		700	5.00	767.81	767.81	9.00	836.91
自卸汽车运土（8t以内）（运距25km以内）	31.25		700	5.00	767.81	767.81	9.00	836.91
砂浆抹面找平	14.36	8.25	2.13	5.00	25.98	233.82	9.00	254.86
采用立邦抗裂防水砂浆，对墙面进行找平	14.36	8.25	2.13	5.00	25.98	233.82	9.00	254.86
涂刷防水涂料2遍	19.86	11.76	2.13	5.00	35.44	637.92	9.00	695.33
涂刷东方雨虹HCA-108屋面外墙高弹性防水涂料1.5mm厚	19.86	11.76	2.13	5.00	35.44	637.92	9.00	695.33
涂刷界面剂	4.77	7.65	1.26	5.00	14.36	215.40	9.00	234.79

墙高界面处理剂	4.77	7.65	1.26	5.00	14.36	215.40	9.00	234.79
外墙表面铲除清理	14.73		2.43	5.00	18.02	270.30	9.00	294.63
对原墙面落灰、起皮的地方进行铲除	14.73		2.43	5.00	18.02	270.30	9.00	294.63
外墙涂料	12.13	8.16	1.97	5.00	23.37	462.73	9.00	504.38
外墙溶剂涂料一底二面	12.13	8.16	1.97	5.00	23.37	462.73	9.00	504.38
39-901南阳台外墙漏水	314.32	161.02	738.6	50.00	1,274.63	3,761.02	90.00	4,099.62
窗口打胶	95.13	65.32	12.41	5.00	181.50	181.50	9.00	197.84
窗口原密封胶铲除，重新打硅宝结构耐候胶	95.13	65.32	12.41	5.00	181.50	181.50	9.00	197.84
堵漏	97.28	45.37	8.54	5.00	158.75	158.75	9.00	173.04
采用YH东方雨虹对缝隙堵漏	97.28	45.37	8.54	5.00	158.75	158.75	9.00	173.04
接缝处打胶	11.65	14.51	4.21	5.00	31.89	242.36	9.00	264.17
对窗台与外墙面接缝处，原密封胶铲除，重新打硅宝结	11.65	14.51	4.21	5.00	31.89	242.36	9.00	264.17
垃圾清理	13.16		3.52	5.00	17.51	105.06	9.00	114.52
人工清理建筑垃圾并装袋，垂直运输短驳	13.16		3.52	5.00	17.51	105.06	9.00	114.52
垃圾装车外运	31.25		700	5.00	767.81	767.81	9.00	836.91
自卸汽车运土（8t以内）（运距25km以内）	31.25		700	5.00	767.81	767.81	9.00	836.91
砂浆抹面找平	14.36	8.25	2.13	5.00	25.98	296.17	9.00	322.83
采用立邦抗裂防水砂浆，对墙面进行找平	14.36	8.25	2.13	5.00	25.98	296.17	9.00	322.83
涂刷防水涂料2遍	19.86	11.76	2.13	5.00	35.44	808.03	9.00	880.75
涂刷东方雨虹HCA-108屋面外墙高弹性防水涂料1.5mm厚	19.86	11.76	2.13	5.00	35.44	808.03	9.00	880.75
涂刷界面剂	4.77	7.65	1.26	5.00	14.36	272.84	9.00	297.40
墙高界面处理剂	4.77	7.65	1.26	5.00	14.36	272.84	9.00	297.40
外墙表面铲除清理	14.73		2.43	5.00	18.02	342.38	9.00	373.19
对原墙面落灰、起皮的地方进行铲除	14.73		2.43	5.00	18.02	342.38	9.00	373.19
外墙涂料	12.13	8.16	1.97	5.00	23.37	586.12	9.00	638.87
外墙溶剂涂料一底二面	12.13	8.16	1.97	5.00	23.37	586.12	9.00	638.87
39-902南阳台外墙漏水	314.32	161.02	738.6	50.00	1,274.63	4,148.67	90.00	4,622.05
窗口打胶	95.13	65.32	12.41	5.00	181.50	544.60	9.00	593.51
窗口原密封胶铲除，重新打硅宝结构耐候胶	95.13	65.32	12.41	5.00	181.50	544.60	9.00	593.51
堵漏	97.28	45.37	8.54	5.00	158.75	317.50	9.00	346.08
采用YH东方雨虹对缝隙堵漏	97.28	45.37	8.54	5.00	158.75	317.50	9.00	346.08
接缝处打胶	11.65	14.51	4.21	5.00	31.89	229.61	9.00	250.27
对窗台与外墙面接缝处，原密封胶铲除，重新打硅宝结	11.65	14.51	4.21	5.00	31.89	229.61	9.00	250.27
垃圾清理	13.16		3.52	5.00	17.51	105.06	9.00	114.52
人工清理建筑垃圾并装袋，垂直运输短驳	13.16		3.52	5.00	17.51	105.06	9.00	114.52
垃圾装车外运	31.25		700	5.00	767.81	767.81	9.00	836.91
自卸汽车运土（8t以内）（运距25km以内）	31.25		700	5.00	767.81	767.81	9.00	836.91
砂浆抹面找平	14.36	8.25	2.13	5.00	25.98	280.58	9.00	305.83
采用立邦抗裂防水砂浆，对墙面进行找平	14.36	8.25	2.13	5.00	25.98	280.58	9.00	305.83
涂刷防水涂料2遍	19.86	11.76	2.13	5.00	35.44	765.50	9.00	834.40
涂刷东方雨虹HCA-108屋面外墙高弹性防水涂料1.5mm厚	19.86	11.76	2.13	5.00	35.44	765.50	9.00	834.40
涂刷界面剂	4.77	7.65	1.26	5.00	14.36	258.48	9.00	281.71
墙高界面处理剂	4.77	7.65	1.26	5.00	14.36	258.48	9.00	281.71
外墙表面铲除清理	14.73		2.43	5.00	18.02	324.36	9.00	353.55
对原墙面落灰、起皮的地方进行铲除	14.73		2.43	5.00	18.02	324.36	9.00	353.55
外墙涂料	12.13	8.16	1.97	5.00	23.37	555.27	9.00	605.24
外墙溶剂涂料一底二面	12.13	8.16	1.97	5.00	23.37	555.27	9.00	605.24
39-902南主卧外墙漏水	314.32	161.02	738.6	50.00	1,274.63	4,074.55	90.00	4,441.26
窗口打胶	95.13	65.32	12.41	5.00	181.50	363.00	9.00	395.67
窗口原密封胶铲除，重新打硅宝结构耐候胶	95.13	65.32	12.41	5.00	181.50	363.00	9.00	395.67
堵漏	97.28	45.37	8.54	5.00	158.75	317.50	9.00	346.08
采用YH东方雨虹对缝隙堵漏	97.28	45.37	8.54	5.00	158.75	317.50	9.00	346.08

接缝处打胶	11.65	14.51	4.21	5.00	31.89	239.81	9.00	261.39
对窗台与外墙面接缝处，原密封胶铲除，重新打硅宝胶	11.65	14.51	4.21	5.00	31.89	239.81	9.00	261.39
垃圾清理	13.16		3.52	5.00	17.51	105.06	9.00	114.52
人工清理建筑垃圾并装袋，垂直运输短驳	13.16		3.52	5.00	17.51	105.06	9.00	114.52
垃圾装车外运	31.25		700	5.00	767.81	767.81	9.00	836.91
自卸汽车运土（8t以内）（运距25km以内）	31.25		700	5.00	767.81	767.81	9.00	836.91
砂浆抹面找平	14.36	8.25	2.13	5.00	25.98	293.05	9.00	319.42
采用立邦抗裂防水砂浆，对墙面进行找平	14.36	8.25	2.13	5.00	25.98	293.05	9.00	319.42
涂刷防水涂料2遍	19.86	11.76	2.13	5.00	35.44	799.53	9.00	871.49
涂刷东方雨虹HCA-108屋面外墙高弹性防水涂料1.5mm厚	19.86	11.76	2.13	5.00	35.44	799.53	9.00	871.49
涂刷界面剂	4.77	7.65	1.26	5.00	14.36	269.97	9.00	294.27
隔离界面处理剂	4.77	7.65	1.26	5.00	14.36	269.97	9.00	294.27
外墙表面铲除清理	14.73		2.43	5.00	18.02	338.78	9.00	369.27
对原墙面落灰、起皮的地方进行铲除	14.73		2.43	5.00	18.02	338.78	9.00	369.27
外墙涂料	12.13	8.16	1.97	5.00	23.37	580.04	9.00	632.24
外墙溶剂涂料一底二面	12.13	8.16	1.97	5.00	23.37	580.04	9.00	632.24
40-701卧室阳台顶渗水	314.32	161.02	738.6	50.00	1,274.63	3,607.27	90.00	3,931.92
窗口打胶	95.13	65.32	12.41	5.00	181.50	363.00	9.00	395.67
窗口原密封胶铲除，重新打硅宝结构耐候胶	95.13	65.32	12.41	5.00	181.50	363.00	9.00	395.67
堵漏	97.28	45.37	8.54	5.00	158.75	158.75	9.00	173.04
采用YH东方雨虹对缝限堵漏	97.28	45.37	8.54	5.00	158.75	158.75	9.00	173.04
接缝处打胶	11.65	14.51	4.21	5.00	31.89	210.47	9.00	229.41
对窗台与外墙面接缝处，原密封胶铲除，重新打硅宝胶	11.65	14.51	4.21	5.00	31.89	210.47	9.00	229.41
垃圾清理	13.16		3.52	5.00	17.51	105.06	9.00	114.52
人工清理建筑垃圾并装袋，垂直运输短驳	13.16		3.52	5.00	17.51	105.06	9.00	114.52
垃圾装车外运	31.25		700	5.00	767.81	767.81	9.00	836.91
自卸汽车运土（8t以内）（运距25km以内）	31.25		700	5.00	767.81	767.81	9.00	836.91
砂浆抹面找平	14.36	8.25	2.13	5.00	25.98	257.20	9.00	280.35
采用立邦抗裂防水砂浆，对墙面进行找平	14.36	8.25	2.13	5.00	25.98	257.20	9.00	280.35
涂刷防水涂料2遍	19.86	11.76	2.13	5.00	35.44	701.71	9.00	764.88
涂刷东方雨虹HCA-108屋面外墙高弹性防水涂料1.5mm厚	19.86	11.76	2.13	5.00	35.44	701.71	9.00	764.88
涂刷界面剂	4.77	7.65	1.26	5.00	14.36	236.94	9.00	258.26
隔离界面处理剂	4.77	7.65	1.26	5.00	14.36	236.94	9.00	258.26
外墙表面铲除清理	14.73		2.43	5.00	18.02	297.33	9.00	324.09
对原墙面等灰、起皮的地方进行铲除	14.73		2.43	5.00	18.02	297.33	9.00	324.09
外墙涂料	12.13	8.16	1.97	5.00	23.37	509.00	9.00	554.81
外墙溶剂涂料一底二面	12.13	8.16	1.97	5.00	23.37	509.00	9.00	554.81
41-801卧室卧室顶渗水	314.32	161.02	738.6	50.00	1,274.63	3,888.84	90.00	3,238.84
窗口打胶	95.13	65.32	12.41	5.00	181.50	363.00	9.00	395.67
窗口原密封胶铲除，重新打硅宝结构耐候胶	95.13	65.32	12.41	5.00	181.50	363.00	9.00	395.67
堵漏	97.28	45.37	8.54	5.00	158.75	158.75	9.00	173.04
采用YH东方雨虹对缝限堵漏	97.28	45.37	8.54	5.00	158.75	158.75	9.00	173.04
接缝处打胶	11.65	14.51	4.21	5.00	31.89	237.26	9.00	258.61
对窗台与外墙面接缝处，原密封胶铲除，重新打硅宝胶	11.65	14.51	4.21	5.00	31.89	237.26	9.00	258.61
垃圾清理	13.16		3.52	5.00	17.51	105.06	9.00	114.52
人工清理建筑垃圾并装袋，垂直运输短驳	13.16		3.52	5.00	17.51	105.06	9.00	114.52
垃圾装车外运	31.25		700	5.00	767.81	767.81	9.00	836.91
自卸汽车运土（8t以内）（运距25km以内）	31.25		700	5.00	767.81	767.81	9.00	836.91
砂浆抹面找平	14.36	8.25	2.13	5.00	25.98	289.94	9.00	316.03
采用立邦抗裂防水砂浆，对墙面进行找平	14.36	8.25	2.13	5.00	25.98	289.94	9.00	316.03
涂刷防水涂料2遍	19.86	11.76	2.13	5.00	35.44	791.02	9.00	862.21
涂刷东方雨虹HCA-108屋面外墙高弹性防水涂料1.5mm厚	19.86	11.76	2.13	5.00	35.44	791.02	9.00	862.21

涂刷界面剂	4.77	7.65	1.26	5.00	14.36	267.10	9.00	291.14
抛高界面处理剂	4.77	7.65	1.26	5.00	14.36	267.10	9.00	291.14
外墙表面铲除清理	14.73		2.43	5.00	18.02	335.17	9.00	365.34
对原墙面落灰、起皮的地方进行铲除	14.73		2.43	5.00	18.02	335.17	9.00	365.34
外墙涂料	12.13	8.16	1.97	5.00	23.37	573.73	9.00	625.37
外墙溶剂涂料一底二面	12.13	8.16	1.97	5.00	23.37	573.73	9.00	625.37
41-902号富南御景水	314.32	161.02	738.6	50.00	1,274.63	4,279.61	90.00	4,664.78
窗口打胶	95.13	65.32	12.41	5.00	181.50	363.00	9.00	395.67
窗口原密封胶铲除，重新打硅宝结构耐候胶	95.13	65.32	12.41	5.00	181.50	363.00	9.00	395.67
堵漏	97.28	45.37	8.54	5.00	168.75	317.50	9.00	346.08
采用YH东方雨虹对缝隙堵漏	97.28	45.37	8.54	5.00	168.75	317.50	9.00	346.08
接缝处打胶	11.65	14.51	4.21	5.00	31.89	257.67	9.00	280.86
对窗台与外墙面接缝处，原密封胶铲除，重新打硅宝纳	11.65	14.51	4.21	5.00	31.89	257.67	9.00	280.86
垃圾清理	13.16		3.52	5.00	17.51	122.57	9.00	133.60
人工清理建筑垃圾并装袋，垂直运输短驳	13.16		3.52	5.00	17.51	122.57	9.00	133.60
垃圾装车外运	31.25		700	5.00	767.81	767.81	9.00	836.91
自卸汽车运土（8t以内）（运距25km以内）	31.25		700	5.00	767.81	767.81	9.00	836.91
砂浆抹面找平	14.36	8.25	2.13	5.00	25.98	314.88	9.00	343.22
采用立邦抗裂耐水砂浆，对墙面进行找平	14.36	8.25	2.13	5.00	25.98	314.88	9.00	343.22
涂刷防水涂料2遍	19.86	11.76	2.13	5.00	35.44	859.07	9.00	936.39
涂刷东方雨虹HCA-108原面外墙高弹性防水涂料1.5mm厚	19.86	11.76	2.13	5.00	35.44	859.07	9.00	936.39
涂刷界面剂	4.77	7.65	1.26	5.00	14.36	290.07	9.00	316.18
抛高界面处理剂	4.77	7.65	1.26	5.00	14.36	290.07	9.00	316.18
外墙表面铲除清理	14.73		2.43	5.00	18.02	361.00	9.00	396.76
对原墙面落灰、起皮的地方进行铲除	14.73		2.43	5.00	18.02	361.00	9.00	396.76
外墙涂料	12.13	8.16	1.97	5.00	23.37	623.04	9.00	679.11
外墙溶剂涂料一底二面	12.13	8.16	1.97	5.00	23.37	623.04	9.00	679.11

