







## 黄泥头佳苑电梯维修方案及报价

施工单位（加盖公章）： 无锡星宇电梯工程有限公司

受损标的： 黄泥头佳苑

受损照片：

|                                                                                     |                                                                                     |                                                                                     |                                                                                     |                                                                                      |
|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|
|    |    |    |   |   |
| 61#左轿显示板                                                                            | 61#右轿显示板                                                                            | 61#左超载装置                                                                            | 61#右超载装置                                                                            | 61#左主导靴                                                                              |
|   |   |   |  |  |
| 61#左主导靴                                                                             | 61#左主导靴                                                                             | 61#左主导靴                                                                             | 61#右主导靴                                                                             | 61#右主导靴                                                                              |
|  |  |  |                                                                                     |                                                                                      |
| 61#右主导靴                                                                             | 61#右主导靴                                                                             | 61#右补偿链                                                                             |                                                                                     |                                                                                      |

施工方案：

1.电梯型号 TKJ800/1.75 18/18/18

2.一楼层门放检修牌

3.切断机房电源，更换新配件，送电调试完成。

报价明细:

| 电梯配件规格型号     | 单位 | 数量  | 单价 (元) | 总价 (元) | 备 注   |
|--------------|----|-----|--------|--------|-------|
| 轿厢内 110%载荷试验 | 台  | 2   | 500    | 1000   | 61#左右 |
| 轿厢显示板        | 套  | 2   | 420    | 840    | 61#左右 |
| 超载装置         | 套  | 2   | 400    | 800    | 61#左右 |
| 主导靴          | 套  | 8   | 480    | 3840   | 61#左右 |
| 补偿链导轮        | 套  | 2   | 365    | 730    | 61#左  |
| 补偿链          | 米  | 140 | 54     | 7560   | 61#右  |
| 更换工时费        | 台  | 1   | 2000   | 2000   | 61#右  |
| 合 计          |    |     |        | 16770  |       |

无锡星宇电梯工程有限公司  
2025年 11 月 6 日

